

DAFTAR PUSTAKA

Evan, James R and William, Lensay (1996)., *The Management and Control of Quality, 3 th edition*, West Publishing Company, Monopolis/St Paul.

Madu, et.al (1996)., "An empirical assessment of the influence of quality dimensions on organizational performance", *International Journal of Production Research.*, Vol. 34, No 7.

Martinich, S. Joseph, (1997)., *Production and Operations Management: An Applied Modern Approach*, John Wiley & Son, Inc.

Mulyadi, (1998)., *Total Quality Management; Edisi pertama*, Aduty Media, Yogyakarta.

Sudjana, 1996, "Metoda Statistika", Transito Bandung, Edisi ke.6.


Vincent, Gaspersz (1998)., *Statistical Process Control : Penerapan Tabeltabel Statiskal dalam Manajemen Bisnis Total*; PT.Gramedia Pustaka Utama, Jakarta.

id.wikipedia.org/wiki/Kualitas

id.wikipedia.org/wiki/Pengendalian_mutu

anak2industri.blogspot.com/.../pengendalian-kualitas.html

petakendali.atSPACE.org/

Lampiran 2. Tabel Distribusi Chi Square (χ^2)Tabel. Nilai kritis distribusi
Khi-Kuadrat

ν	α							
	0,995	0,99	0,975	0,95	0,05	0,025	0,01	0,005
1	0,00393	0,0157	0,01982	0,02393	3,841	5,024	6,635	7,879
2	0,0100	0,0201	0,0506	0,103	5,991	7,378	9,210	10,597
3	0,0717	0,115	0,216	0,352	7,815	9,348	11,345	12,838
4	0,207	0,297	0,484	0,711	9,488	11,143	13,277	14,860
5	0,412	0,554	0,831	1,145	11,070	12,832	15,086	16,750
6	0,676	0,872	1,237	1,635	12,592	14,449	16,812	18,548
7	0,989	1,239	1,690	2,167	14,067	16,013	18,475	20,278
8	1,344	1,646	2,180	2,733	15,507	17,535	20,090	21,955
9	1,735	2,088	2,700	3,325	16,919	19,023	21,666	23,589
10	2,156	2,558	3,247	3,940	18,307	20,483	23,209	25,188
11	2,603	3,053	3,816	4,575	19,675	21,920	24,725	26,757
12	3,074	3,571	4,404	5,226	21,026	23,337	26,217	28,300
13	3,565	4,107	5,009	5,892	22,362	24,736	27,688	29,819
14	4,075	4,660	5,629	6,571	23,685	26,119	29,141	31,319
15	4,601	5,229	6,262	7,261	24,996	27,488	30,578	32,801
16	5,142	5,812	6,908	7,962	26,296	28,845	32,000	34,267
17	5,697	6,408	7,564	8,672	27,587	30,191	33,409	35,718
18	6,265	7,015	8,231	9,390	28,869	31,526	34,805	37,156
19	6,844	7,633	8,907	10,117	30,144	32,852	36,191	38,582
20	7,434	8,260	9,591	10,851	31,410	34,170	37,566	39,997
21	8,034	8,897	10,283	11,591	32,671	35,479	38,932	41,401
22	8,643	9,542	10,982	12,338	33,924	36,781	40,289	42,796
23	9,260	10,196	11,689	13,091	35,172	38,076	41,638	44,181
24	9,886	10,856	12,401	13,848	36,415	39,361	42,980	45,559
25	10,520	11,524	13,120	14,611	37,652	40,646	44,314	46,928
26	11,160	12,198	13,844	15,379	38,885	41,923	45,642	48,290
27	11,808	12,879	14,573	16,151	40,113	43,194	46,963	49,645
28	12,461	13,565	15,308	16,928	41,337	44,461	48,278	50,993
29	13,121	14,256	16,047	17,708	42,557	45,722	49,583	52,336
30	13,787	14,953	16,791	18,493	43,773	46,979	50,892	53,672

† Disalin dari Tabel 18 *Biometrika Tables for Statisticians*, Jilid I scizin E. S. Pearson dan Biometrika Trustees.

DAFTAR HARGA – HARGA D3 DAN D4 UNTUK DIAGRAM KONTROL R

n	D3	D4	n	D3	D4
2	0	3,267	14	0,329	1,671
3	0	2,575	15	0,348	1,652
4	0	2,282	16	0,364	1,636
5	0	2,115	17	0,379	1,621
6	0	2,004	18	0,392	1,608
7	0,076	1,924	19	0,404	1,596
8	0,136	1,864	20	0,414	1,586
9	0,184	1,816	21	0,425	1,575
10	0,223	1,777	22	0,434	1,566
11	0,256	1,744	23	0,443	1,557
12	0,284	1,716	24	0,452	1,548
13	0,308	1,692	25	0,459	1,541

Sumber: E.G. Kirpatrick, Quality control for Managers and Engineer, John Wiley & Sons Inc., N.Y., 1970

PRODUCTION FLOWCHART

